

New Enhanced Service Bulletins

by Mark Baker, Tim Dowling, Willard Martinez, Tom Medejski, Dan Pedersen and Don Rockwell, Service Bulletin Engineering

Increasing economic and regulatory pressures make it imperative for airlines to find opportunities to reduce costs and show conformance to manufacturer's data. Because airline maintenance operations represent a significant cost, airlines have asked Boeing for help in reducing this cost. Recent results show that changing the way service bulletins are prepared and delivered – combined with airline process improvements – can reduce maintenance cost significantly and improve the ability to show conformance.

Boeing has continually made enhancements to the content, format, and delivery of its service bulletins. Past enhancements include digital delivery, simplified English, and tabular work instructions.

Boeing has been working directly with airlines to reduce end-to-end costs for service bulletin incorporation. During this process, it was observed that when airlines create their engineering orders, they rewrite or reengineer service bulletins and rekit or repackage the kit of parts to match their own engineering orders. This reengineering causes unnecessary delays and expense for the airlines in implementing service bulletins.

Boeing developed the "Enhanced Service Bulletin," also known as the "Next Generation Service Bulletin," to minimize this reengineering effort while making it easier and less expensive to implement service bulletins. The enhanced service bulletin, in conjunction with airline process improvements, will enable a smooth workflow ensuring that information, parts, and tools are staged in a coordinated manner to support the mechanic during service bulletin incorporation.

Boeing's enhanced service bulletins incorporate four key features: lean work instructions, faster access to essential information, improved kit packaging, and selective information extraction. These features have been incrementally introduced into Boeing service bulletins as they became available beginning in mid 2003. Today, Boeing develops all new service bulletins to encompass all four features whenever possible.

FOUR KEY FEATURES REDUCE AIRLINE ENGINEERING, PLANNING, AND OPERATIONS COSTS ASSOCIATED WITH SERVICE BULLETIN INCORPORATION. 01.

Lean work instructions

One of the most apparent changes in the enhanced service bulletin is that figure instructions are provided in a work breakdown of four hours or fewer. This makes it possible for airlines to schedule mechanics' time more efficiently and reduces the coordination difficulties associated with work shift changeover.

Each figure in the enhanced service bulletin is a single configuration. Previously, multiple configurations were typically shown in a figure. This required the airline engineer, planner, or mechanic to extract the steps applicable to the specific airplane. One configuration per figure simplifies extraction of the applicable data and can prevent accomplishment of the wrong steps. Additionally, separate left and right side figures are now provided, which further facilitates extraction of the applicable data.

03.

Improved kit packaging

Enhanced service bulletin kits are packaged to match the figure instructions. If operators use the service bulletin instructions as written, this new packaging eliminates additional repackaging or sorting through parts. This change alone can result in a significant time savings in both the operations and maintenance arenas.

02.

Faster access to essential information

When viewed online, Boeing's enhanced service bulletins include hotlinks within their text that provide direct access to referenced documents, making it easier and faster to find the information needed. For example, hotlinks provide quick access to relevant information in the Airplane Maintenance Manual (AMM), Structural Repair Manual (SRM), and other documents available on the Web portal MyBoeingFleet.com.


04.

Selective information extraction

Enhanced service bulletins enable airline personnel to extract information specific to selected airplane configurations. This allows an airline to more quickly identify and extract service bulletin information specific to its airplane configuration. Once the data is extracted, it can easily be copied into an airline's own document management system.



The HTML file provides hotlinks to maintenance documentation referenced in the service bulletin and the ability to quickly



Doeing Service Bulletin 777-54-0021 Table of Centents - Summary - Planning - Materials - Accomplishment Instruction: Filter By Geoop - View PDF - View Effectivity - FAOs - Back To Search BOISING RECOMMENDS THAT EACH OPERATOR EXAMINE THIS SERVICE BUT Filter This Service Bulletin By Group Step 1 - Deselect group/configuration options to filter this senice bulletin. Stops for these groups/configurations will be shown St Show All Groups (do not filter this Service Bulletin) Greep 1: Airplane line number 6 through 503, 505 and 506 s Ceefig 1: Airplane line number 6 through 373 with the heat shield blanker and cover place Ceeffig 2: Airplanes 421, 424 - 427, 435, 436, 435 been changed to use subplates on the Coafig 3: All airplanes line number 6 through 506 Greep 2: Airplane line number 2 through 505 with Pratt and Step 2 - View the filtered Senice Belletin. The filter will remain on until you ret

0.0.320 Phe 9-13 E-13

- Planning
 Motensis
 Accomplishment instructions
 Eigene Index

How Does Filter By Group Work?

The "Filter by Group" feature for HTML Service Bulletins allows you to select a


Example: You are working on an arcraft that belongs to Group 1 and want to Instructions link. A barner is displayed at the top of the page that says "Service"

The parts of the Service Bulletin that are filtered are as follows:

- Planning Information
 Materials Information
 Accomplishment Instructions
 Figure Index (6 present)
 Appendix Index (6 present)

All other sections of the Service Bulletin (Summary, Revision Transmittal Info., the filter by distribution the "filter file Cares" link in the more has need they project

THE "FILTER" FUNCTION ALLOWS AIRLINES TO EXTRACT DATA BY INDIVIDUAL AIRPLANE GROUP AND CONFIGURATION.



BENEFITS OF THE BOEING ENHANCED SERVICE BULLETIN

Boeing worked with airlines to validate the benefits of the enhanced service bulletin. As part of that effort, Boeing coordinated closely with one airline to study the predicted benefits of the enhanced service bulletin. Study data from the airline showed these predicted benefits:

- A potential 60 percent reduction in defects attributed to the rewriting or reengineering of the service bulletin data into the airline's document management system.
- A potential 77 percent reduction in labor hours to develop and release the service bulletin data into the airline's document management system.

Based on the positive results of the study data, Boeing continued to work closely with the same airline to collect actual labor hour benefits. The actual data was obtained by comparing airline incorporation of a conventional service bulletin on part of its fleet and an enhanced version of the same service bulletin on the remainder of its fleet. Data from the airline showed these actual results:

- A reduction in nonrecurring engineering labor hours to develop the airline's own engineering and job cards from 143 labor hours to 87 labor hours.
- A reduction in recurring kit packaging labor hours from 24 hours to 6 hours per airplane.

ENHANCEMENTS CONTINUE

To date, Boeing has issued more than 1,300 service bulletins across all Boeing model airplanes with one or more of the four key features described above. Boeing has been working with a number of airlines to assist in the adoption and implementation of enhanced service bulletins into their operations as well as to obtain airline user feedback. Such feedback is key to adding improvements to the enhanced service bulletins.

SUMMARY

Boeing understands that each airline's maintenance operation is unique and is willing to work with individual airlines to ensure that each leverages all of the benefits possible from enhanced service bulletins and that the bulletins fit well with existing airline operations. Airlines may contact their Boeing Field Service Representative for assistance in adopting enhanced service bulletins. For more information, contact Dan Pedersen at dan.w.pedersen@boeing.com.